



CONDITION INTELLIGENCE® EXPERT INSIGHTS

Watch out for these fault effects in C27s, which can reduce engine life:

- ✓ Low level fuel dilution– check for leaking injector seals
- ✓ Slight cylinder washout caused by low level fuel dilution–monitor iron levels (ppm)
- ✓ Significant engine de-rates– look for buildup on pressure sensor in engine valley

For additional insights on C27 ACERT® engines, contact us at benchmarks@dingo.com


CAT C27 ACERT ENGINE LIFE WHEN USED IN CAT D10T DOZERS

WITHOUT DINGO

WITH DINGO

COMPONENT COUNT

+23%



AUSTRALIA
16 Macgregor Street
Wilston QLD 4051
+61 7 3115 9000

CANADA
Ste 182 315, 5155 130th Ave.
SE Calgary AB T2Z 0N3
+1 888 346 4630

USA
6970 S. Holly Circle, Ste 200
Centennial, CO 80112
+1 888 346 4630