



### CONDITION INTELLIGENCE® EXPERT INSIGHTS

Watch out for these fault effects on the QSK60, which can reduce engine life:

- ✓ ROS issues, resulting in oil breakdown and excessive bearing wear / high lead levels
- ✓ Exhaust manifold bolts bend and shear due to heat – testing stainless bolts
- ✓ Using incorrect parts on oil spinner


For additional insights on Cummins QSK60 engines, contact us at [benchmarks@dingo.com](mailto:benchmarks@dingo.com)

## CUMMINS QSK60 ENGINE LIFE WHEN USED IN KOMATSU 830/930E HAUL TRUCKS

WITHOUT DINGO

WITH DINGO

COMPONENT COUNT



AUSTRALIA  
16 Macgregor Street  
Wilston QLD 4051  
+61 7 3115 9000

CANADA  
Ste 182 315, 5155 130th Ave.  
SE Calgary AB T2Z 0N3  
+1 888 346 4630

USA  
6970 S. Holly Circle, Ste 200  
Centennial, CO 80112  
+1 888 346 4630