



**CONDITION INTELLIGENCE®
EXPERT INSIGHTS**

Watch out for these common fault effects, which can reduce engine life:

- ✓ Abnormal Combustion & Fluid Condition Deterioration due to biofuel usage, extended idle times, and high operating temperatures
- ✓ High Wear Metals due to bushing, thrust washer, or bearing wear; common in Cummins QSL 8.9 engines

Cummins QSL 8.9 Engines when used in Tamrock EJC 30SX Haul Trucks

Customer Average before DINGO
3,306 hours

Average under DINGO management
7,483 hours

