



Watch out for these fault effects in C27s, which can reduce engine life:

CONDITION INTELLIGENCE®
EXPERT INSIGHTS

- ✓ Low level fuel dilution– check for leaking injector seals
- ✓ Slight cylinder washout caused by low level fuel dilution–monitor iron levels (ppm)
- ✓ Significant engine de-rates– look for buildup on pressure sensor in engine valley


CAT C27 ACERT ENGINE LIFE WHEN USED IN CAT D10T DOZERS

WITHOUT DINGO

WITH DINGO

COMPONENT COUNT

+23%



For additional insights on CAT C27 Acert engines or any other equipment in your fleet, contact us at info@dingo.com. Or visit DINGO.com to learn more about how your mine can save millions with our industry leading predictive maintenance solutions.