



CONDITION INTELLIGENCE® EXPERT INSIGHTS

Watch out for these fault effects on the 3516, which can reduce engine life:


- ✓ Abnormal camshaft wear – look for wear metals in oil samples
- ✓ Broken cylinder rings – shows in exhaust temp differential
- ✓ Intake system leaks – monitor by pressurizing intake to 10 psi max & inspect for leaks

For additional insights on CAT 3516 engines, contact us at benchmarks@dingo.com

CAT 3516 ENGINE LIFE WHEN USED IN CAT 793 HAUL TRUCKS

WITHOUT DINGO

WITH DINGO



AUSTRALIA
16 Macgregor Street
Wilston QLD 4051
+61 7 3115 9000

CANADA
Ste 182 315, 5155 130th Ave.
SE Calgary AB T2Z 0N3
+1 888 346 4630

USA
6970 S. Holly Circle, Ste 200
Centennial, CO 80112
+1 888 346 4630