



Watch out for these fault effects on the QSK60, which can reduce engine life:

CONDITION INTELLIGENCE®
EXPERT INSIGHTS


- ✓ ROS issues, resulting in oil breakdown & excessive bearing wear / high lead levels
- ✓ Exhaust manifold bolts bend and shear due to heat – testing stainless bolts
- ✓ Using incorrect parts on oil spinner

CUMMINS QSK60 ENGINE LIFE WHEN USED IN KOMATSU 830/930E HAUL TRUCKS

WITHOUT DINGO

WITH DINGO

COMPONENT COUNT



For additional insights on Cummins QSK60 engines or any other equipment in your fleet, contact us at info@dingo.com. Or visit DINGO.com to learn more about how your mine can save millions with our industry leading predictive maintenance solutions.